



SERVICE BULLETIN

Title: Guide Vane Crank Arm

Models Affected: 19DK, 19DM, 19EB4, 17/19FA4, 19HR

Number: C9109

Date: 7/15/91

Supersedes: None

Date:

Purpose:

To provide the instruction necessary to correct the slippage problem with some existing guide vane crank arms as described in Service Bulletin C9005, dated March 15, 1990. To inform the field of a design change regarding the crank arm.

File: Compressor–Motor Assembly

Prepared By: Todd Young

Approved By: Alan M. Johnson


This document and the material contained herein are the property of Carrier Corporation and may not be copied, reproduced, or released without written permission of Carrier Corporation.

Background:

During March 1988, the guide vane crank arm and drive shaft underwent design changes in an effort to eliminate slippage problems. In some instances, however, slippage problems are still being reported. In order to completely eliminate this problem, the new crank arm is going through a slight modification during production. This modification increases the gap clearance from 0.062" to 0.125" allowing the crank to exert more clamping pressure around the drive shaft when the hex screw is tightened. The part no., 19DM212-1322, has not changed.

Procedure:

If a new guide vane crank arm slips, machine the gap clearance to 0.125. This gap clearance is illustrated in the accompanying drawing.



PART NO. 19DM212-1322
GUIDE VANE CRANK ARM