



**UNITED
TECHNOLOGIES
CARRIER**

Commercial Division
Carrier Corporation

BULLETIN: CA-SB-17-72-20

DATE: 7/7/72

PAGE: 1 OF 2

SERVICE BULLETIN

SUBJECT:

17M,P,S CONTACT SEAL GUIDE RING

**SUPERSEDE
BULLETIN:**

DATE:

PAGE: OF:

Installation, repair and service and equipment referenced in this Service Bulletin should be undertaken only by qualified persons. Carrier Corporation (1) makes no representations or warranties, expressed or implied, concerning the accuracy, completeness or right to use the information contained herein, and (2) disclaims all liability for injuries, damages, infringements and other losses which may arise on account of, or which may result from, the use or application of any information, method or apparatus disclosed herein.

PURPOSE

To transmit the correct and up-to-date guide ring hole sizes.

MACHINES AFFECTED

17M,P,S compressors with contact seal.

PROCEDURE

The chart on Figure 1 gives the nine possible guide rings with their respective hole sizes and number of holes. If a guide ring with a part number other than one of those listed is found, contact your Replacement Components Division Account Representative for assistance.



**UNITED
TECHNOLOGIES
CARRIER**

Commercial Division
Carrier Corporation

BULLETIN: CA-SB-17-72-20

DATE: 7/1/72

PAGE: 2 OF 2

SERVICE BULLETIN

SUPERSEDE
BULLETIN:

DATE:

PAGE: OF:

TABLE OF GUIDE RINGS

GUIDE RING	HOLE SIZE	NO. OF HOLES
17M32-2033	5/64"	3
17M42-2073	3/32"	3
17M42-2422-1	5/64"	3
17M52-2103	5/64"	3
17M52-3042	1/16"	2
17S32-1902	3/32"	3
17SA32-2013	5/64"	3
17M421-1103-1	7/64"	3
17M421-1373	7/64"	3




FIGURE 1