



**UNITED
TECHNOLOGIES
CARRIER**

Commercial Division
Carrier Corporation

BULLETIN: CA-SB-19-C-68-47
DATE: 7/3/69
PAGE: 1 OF: 1

SERVICE BULLETIN

SUBJECT:

19C, R-114 VANE QUICK-CLOSE SOLENOIDS

SUPERSEDE
BULLETIN:
DATE:
PAGE: OF:

Installation, repair and service and equipment referenced in this Service Bulletin should be undertaken only by qualified persons. Carrier Corporation (1) makes no representations or warranties, expressed or implied, concerning the accuracy, completeness or right to use the information contained herein, and (2) disclaims all liability for injuries, damages, infringements and other losses which may arise on account of, or which may result from, the use or application of any information, method or apparatus disclosed herein.

PURPOSE

To advise of a modification to the 19C R-114 machine.

MACHINES AFFECTED

All 19C R-114 machines.

INFORMATION

The quick-close solenoid valve vendor has discontinued production of the valve.

These valves will no longer be installed on the R-114 machines. If a valve fails in the field, remove it, and cap the oil line. Both valves may be removed if desired.